

TITH the rapid changes and new circuits being introduced in the growing television industry. the TV technician is compelled to develop new and modern servicing techniques to keep pace. A troubleshooting procedure, based on the picture tube as a source of Information, has been developed by C. W. Hoshour, director of service, Belmont Radio Corporation, and presented in recent lectures to technicians throughout the

It is a known fact that a good radio technician can shoot trouble in a radio receiver by simply using his ears. He can translate into circuitry, what he hears and usually But his finger on the trouble. By the same token, a TV Mchnician can use his eyes to ferret out service faults. The picture tube is an important and readily available piece of test equipment and it furnishes a great deal of servicing information. If the TV technician knows in what way the Various circuits contribute to a normal television picture. he can, by viewing the face of the picture tube, determine what particular circuit is causing a certain trouble. The shility of a technician to interpret what he sees on the face of the picture tube will provide him with a quick, easy,

and modern method of television troubleshooting. The test patterns reproduced in this and the articles to follow are actual photographs of the picture tube of an simulated in the receiver to give the desired results. Only a few were touched by the artist's brush as the desired conditions could not be set up at the time. The test pattern used is the RCA "Indian-Head" superimposed on a Pattern consisting of 24 dots horizontally and 14 dots ver-

Fig. 1. Normal picture. It is clear, steady, with proper con-



Part I of a three-part series. How the test pattern on the picture tube can be used to isolate the trouble. Once you have learned to interpret what you see, servicing is simplified.

tically obtained from a composite video and r.f. generator at Belmont Radio. Fig. 1 is the average television picture that can be seen

on any normally operating receiver in a local signal area. Obtaining a good television picture depends on the following factors; station transmission limitations, receiver design and adjustments, signal strength, and antenna installation. The station transmission curbs greatly limit the over-all quality of a television picture. Present FCC standards limit the system in bundwidth and resolution and provide a picture which is equivalent to 16 mm film. A 16 mm film has approximately 250,000 picture elements whereas the standard 35 mm movie film has approximately 1,000,000 elements. Thus picture quality is limited because of present transmission standards and "movie quality" should not be expected.

Receiver design and adjustments also play an important role in obtaining a good picture. A receiver should have a tuner with ample gain and a high signal-to-noise ratio, i.f.

Fig. 2. An example of ghosts or multiple images. The images at the far left is the original unreflected signal while the various displaced images to the right are reflected pictures.











and video amplifiers of sufficient gain and handpass it obtain all the reproducible frequencies, a good age, ryitem to prevent overloading in strong signal areas and taking in weaker signal locations, and good sync circuits is order to avoid poor synchronization. Receiver adjustment to fill the screen and give reasonable linearity, r.f. and if alignment, centering, focus, and proper contrast are also important and must be made in order to obtain a good

Signal strength will depend mainly upon the distance Signal strength will depend mainly upon the distance that the strength of the strength of the strength of the surresting strength of the ghosts. As a general rule, picture quality will improve with increased strength strength of the strength of the

Antenna installations will vary with the signal strength available. In low signal areas much more attention must be given to the installation. Such points as height, orientation, length and matching of transmission line, and gale of the antenna must be considered to obtain a good television picture.

There are four basic tyces of outside interference while

are detrimental to a good picture. Their effect on the picture is easily discernible but in many cases the interference can be minimized or eliminated. Many article have been written on these various types of interference therefore, only the more important points will be covered in this series. These four types of interference are quite common but since they cause considerable trouble for the technician, they are worthy of consideration.

Ghosts or multiple images are transmitted signals while are reflected from buildings, mountains, or other objects in the vicinity and reach the antenna at different time in the vicinity and reach the antenna at different time in a shown in Fig. 2. Fig. 2 represents the state of the three reflected signals. The image at the far left is the registal unreflected signal. The open has stabilized on the first ghost reflection and it has greater signal strength. The state of the state of

There is no set or standard procedure for climinating ghosts. There are many solutions that have proved socious that to various heatines. However, the same solution section. In overall, the same solution error method sites provide to the best procedure, it is as area where ghosts are present, orienting or rotating the anatesan samp supposeds a stronger unreflected signal and soatesan samp supposeds a stronger unreflected signal and the santenan storage the source of reflection rather than the station may post the source of reflection rather than the station may one installing a more directional type antennas, using separate channel antennas, installing an antenna rotor, matching the santenan to the receiver, connecting a shorted quarter than the procedure, and the santenant to the receiver, connecting a shorted quarter than the procedure of the santenant to the receiver, connecting a shorted quarter than the santenant to the receiver, connecting a shorted quarter than the santenant to the receiver, connecting a shorted quarter than the santenant to the receiver, connecting a shorted quarter than the santenant to the santenant t

ing the correct transmission line length.

One other solution may be to relocate or move the antenna. In some cases, moving the antenna only a fee
tenna. In some cases, moving the antenna only a fee
ted completely eliminated all traces of ghosts. The distance
to the condition of the control of the control
tance and direction the antenna should be moved to
take the control
tance and trace of the control
tance the control

Fig. 3. An example of r.f. interference. Narrow, evenly-spaced bars appear diagonally between a vertical or horizontal position. Bars may be wavy or bent and vary widely in number.

Fig. 4. Ignition interference causes sporadic black and white streaks in the horisontal direction. They move vertically and at random with no particular pattern discernible on the screen.

Fig. 5. Digithermy interference produces or harringbone pottern which were pour of the picture in a horizontal pinne. This is questionly syncial vertically and may also move vertically. Fig. 6. Mistuning, foulty unisona installation in trape crees, or overloading causes white following black portions of pic-

ture to appear as ghosts with poor over-all definition. May be accompanied by poor sync and horizontal pulling of raster.

HADDO & TELEVISION NEWS

Fig. 7. Normal fringe reception characterised by lack of contrast accompanied by snow and, in some cases, susceptibility to r.L. interference. Good horizontal and vertical sync stability is difficult to obtain under such fringe area conditions.

Fig. 8. Ghosts and weak signal conditions are apt to cause snow.

Fig. 9. An example of 80-cycle hum. The light and dark shadlog of the picture in the horizontal plane usually exists only when a picture signal or carrier is present at the r.l. input.

Fig. 10. Sound bars. Intermittent light and dark shadings of picture in horizontal plane may or may not move vertically.

width corresponds to approximately 9½ miles of the delayed distance traveled by the reflected signal. Displacement of the ghosts, illustrated in Fig. 2, as related to pictize width shows an approximate delay of ½ mile. Knowag the additional distance traveled may assist in deter-

mining the reflecting source. A case of r.f. interference is usually caused by a strong signal whose frequency is higher than the station's retrived video carrier. The strong signal may be radiated and nicked up from high powered radio equipment in the vicinity, local oscillator in a nearby receiver, or radio from ham equipment. The interfering signal beats with the video carrier thus producing a "difference" frequency fall-ing within the video range. The higher the interfering sgnal is above the video carrier the narrower and more firmerous the diagonal lines. An interfering signal ap-Proximately 3 megacycles above the video carrier is illustrated in Fig. 3. This type of interference may not affect every station and may vary from station to station in different locations. One point of interest to remember oncerning r.f. interference is that the amount of picture interference is governed by both the signal strength of the Station and the strength of the interfering signal. The stronger the station signal the less will be the effect of the interfering signal.

Such r.f. inferference may also be caused by radiation flum video detectors climilar to heterophe "tweet" in bradeast receivers) and sound discriminators or r.f. high the attentation of the receivers of the receiver may help reduce the interference. In agarting, the receiver may help reduce the interference. In agartlike, the use of a mater antenna system completely elimilates this problem. Not much can be done to eliminate Lit interference undess corrective measures are taken at a Lit interference undess corrective measures are taken at the contractive of the receiver of the receiver of the littling this type of interference include the installation of a room directional, higher gain antenns, the use of ware

to reduce pick-up.

Lentino type Interference, characterized by black or while streaks running across the picture (Fig. 4), is generally due to breaking contact-type electrical equipment Sen at the lightin systems of trucks and cars, cash regislers, electric razors, vacuum cleaners, or adding machines, the electric razors, vacuum cleaners, or adding machines, Mission line or can come in through the power line. A lower line filter installed between the receiver and wall solute will usually eliminate the power line as a source of

season line or car contained by the contained and the contained and cont

due to corona or arcing in the high voltage supply.

Blathermy interference, Fig. 5, is generally caused by reliation from x-ray equipment, commercial r.f. heating with the properties of the p

(Continued on page 150)









DUAL POWER SUPPLY Power Transformer Bargains 115 Volt, 40 Cy. Pri on, \$7.899 45 san \$3.75 Mobile Use. SPDT \$0.99 . \$5.75 MICROAMMETERS PANEL 3" METERS METERS W GOY'T SURPLUS *Special Scale KV 80. 3175 2" GF Voltmeter 0-30 Veits DC Aircraft OIL CONDENSERS OIL CAPACITOR SPECIAL MFD 1200 VOC 1% W. W. Resisters 1 2K. 8500 FILAMENT BAXELITE CASED MICAS WOUND RESISTORS

IN THE PROPERTY OF THE PROPERT

Phone COrtlandt 7-6443-4

Interpreting TV Patterns (Continued from page 37)

Outside interferences (sexuluting phots) when caused by radiation of electrical equipment will affect the electrical equipment will affect the picture only when such equipment is in operation. Time and effort are required to track down the appliance or equipment causing the interference, the end of the end

the contacts, or by installing a booster at the receiver or detuning the i.f.'s. Since the market for television receivers has almost reached the saturation point in metropolitan areas, TV distributors and dealers are now emphasizing sales in the suburbs and in nearby communities. Technicians will have to face the problem of poor reception in these fringe areas. The cause of pictures like those shown in Figs. 6. 7, and 8, is weak signal strength. Technicians have often modified receivers in order to increase gain and improve the over-all picture quality. These design changes are commendable only insofar as they produce the desired results. The best method is to increase the signal strength at the antenna terminals of the receiver. Since an antenna installation must often be a compromise because of the cost involved, receiver modifications such as substituting higher gain r.f. or i.f. tubes, removing or decreasing a.g.c. to the r.f. or i.f. stages, and realignment to decrease bandwidth and increase gain may be tried to obtain a more favorable picture. Before receiver modifications are attempted, the customer should be advised that while the changes will produce a better picture in the present location, if the receiver is moved to a stronger signal area or if at a later date the signal strength is increased, the receiver may not perform satisfactorily because of the modifications.

Fig. 6 Illustrates the results et a faulty antenna installation and station interference in fringe reception areas. In local signal areas this condition may be due to lack of care when tuning is a station, generally tuning to the low frequency side of the signal rather hand to be a station of the signal rather hand to be a signal rather and the signal rather hand to be a signal rather and the signal caused by a loss of a.g., gasy it, tubes, or a defective video amplifies stage. This condition may also be caused by a low-voltage filter coccaused by a low-voltage filter coc-

denser which produces 120-cycle house The normal frings reception tax pattern of Fig. 7 is the pattern which may be expected on the screen of a receiver operating in a low signal area, a condition existing in fringe areas. In local signal areas this condition may be caused by a weak or deaf rf. tube in the tuner, i.f. tubes, or associated components.

Ghosts combined with a weak signal condition (Fig. 8) can generally be found in receivers which are operating on inside or built-in antennas in apart. ment buildings where an outside antenna is not permitted. This condition nas are installed in valleys or are loin almost complete shielding of the antenna from the signal source. condition may also be caused by a broken or shorted transmission line Possible solutions to improve reception include installing an outside antenna where possible, increasing the height of the antenna, re-orienting or relocating the antenna, installing a booster, or performing receiver modifications to increase gain.





Fig. 11. Schematic of the tuner used in a current Raytheon television receiver.

Fig. 12. The video i.f. amplifier incorporated in a recent Raytheon video set.



A 60-cycle hum is generally due to a short or leakage between the cathode and filament in the i.f. or video amplifier tubes (See Fig. 9). The hum will be noticeable only when receiving a nicture (raster will appear normal) if an if tube is at fault or may be present at all times if a filament-tocathode leakage exists in the video amplifier stage. This condition is also possible when one-half of the low voltare nower transformer secondary is inoperative or when one-half of the low voltage rectifier is defective causing a condition similar to that produced by a poorly filtered half-wave supply. Radiation from a 60-cycle sweep generator being operated near the receiver should not be overlooked as a possible source of the trouble. Substitution of i.f. or video amplifier tubes is a quick solution. One other method is to short the cathode of each defective tube to ground. Start with the higher gain tubes first and test only those tubes that are above ground with respect to 60 cycles. A short or leakage between cathode and filament will immediately show up.

Another common annovance to the TV viewer is sound bars (Fig. 10). Sound hars may be caused by mistuning of the receiver microphonic station camera equipment, a microphonic vertical oscillator tube, or microphonic a.g.c. controlled r.f. and i.f. tubes. A microphonic vertical oscillator will cause compression and expansion of the scanning lines which results in light and dark shadings. (A microphonic horizontal oscillator tube will produce a sideward displacement.) Brilliance modulations which show up as light and dark shadings are caused by microphonic r.f. or i.f. tubes which will not respond to vibration without signal. One simple method of determining which section of the receiver is at fault is to tune to an off channel and iar the cabinet. If the sound bars are no longer present an r.f. or i.f. tube is microphonic. If, however, the sound bars remain, the vertical oscillator tube is at fault. Once the troublesome

section is found, tab the times distributed interphonic tube is located. Replacement, obviously will cure the trouble. In Part 2 of this series the video amplifier, a.g.c. system, sync, and vertical deflection circuits will be analyzed, using the picture tube as the source of

(To be continued)

NEW OFFICERS NAMED

THE Florida Association—R & TTG has elected the following officers to serve one-year terms.

President Steven Petruff will have Shan Beajardines as his vice-president. Thomas M. Middleton as secretary, and A. Ed Stevens as treasurer. Board memhers include: John Gilbert, Samuel Kessler, C. E. Lawrence, John J. Petruff, Chao. Pierce. Glem Ryan, and The association voted to affiliate with NETSDA. SAVE! QUALITY TRANSFORMERS-UP TO 751 OFF!







GROERING DIRECT